



Fuse Box			
Work Lamp	5A		
Oil Pressure Lamp	5A		
Hour Meter	5A		
Relay Coil	5A		
Horn	30A		
Fuel Cut-off			
Main			

Color Codes			
Black	-B	White	-W
Red	-R	Green	-G
Yellow	-Y	Brown	-Br
Blue	-L	Orange	-O
Pink	-P	Light Green	-Lg
Violet	-V	Sky Blue	-Sb

Wires are of AVS or CAVS type, of 0.5 size unless otherwise noted.



配線図 (DIAGRAM) ~ No.7305161


フェーズボックス  
Fuse Box

Main	Relay Cut-off	Hour Meter	Oil Pressure Lamp	Work Lamp
30A	5A	5A	5A	5A

Color Codes

Black	-B	White	-W
Red	-R	Green	-G
Yellow	-Y	Brown	-Br
Blue	-L	Orange	-O
Pink	-P	Light Green	-Lg
Violet	-V	Sky Blue	-Sb

Example: WB  
Wire size of AVS or CAVS type, of 0.5 size unless otherwise noted.



配線図(DIAGRAM)No.7305162~